Bridgeboro Historic District Charles Gaskill House 14 South Bridgeboro Street Bridgeboro Burlington County N.J

HABS No. NJ-899-2

HABS NJ, 3-BRIBO, 1/2-

Photographs

Written Historical and Descriptive Data

HISTORIC AMERICAN BUILDING SURVEY
NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
WASHINGTON DC, 20240

ited States Department of the Interior eritage Conservation and Recreation Service Vashington, D.C. 20243

Eligibility on 6/26/81.

Dennis DeGregory, N. J. Department of Transportation

COMPILER, AFFILIATION

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY HABS

DATE

9/30/82

ARCHITECTURAL DATA FORM

3-BR180,

STATE New Jersey	COUNTY Burling	COUNTY Burlington		TOWN OR VICINITY Bridgeboro-Delran Townships	
HISTORIC NAME OF STRUCT Bridgeboro Historic Charles Gaskill House	URE (INCLUDE SOUR District e (1860 Lake & Bee	CE FOR NAME) rs map of Burling	ton County)	MABS NO. NJ-899-2	
SECONDARY OR COMMON NAM Langer House (1979)	ES OF STRUCTURE			· ·	
COMPLETE ADDRESS (DESCR	IBE LOCATION FOR	RURAL SITES)			
14 South Bridgeboro S	Street				
DATE OF CONSTRUCTION (I Before 1860 (Lake & E	NCLUDE SOURCE) Beers 1860 Map)	ARCHITECT(S) (IN Unkno		•	
SIGNIFICANCE (ARCHITECT	URAL AND HISTORIC	AL, INCLUDE ORIG	TNAL USE OF STE	RUCTURE)	
Part of the Bridgebor					
century buildings in residence in 1860.	Bridgeboro. The 1	property was orig	inally the Char	les Gaskill	
STYLE (IF APPROPRIATE) Vernacular			, <u> </u>		
MATERIAL OF CONSTRUCTION 2½ story wood frame w	N (INCLUDE STRUCT) with asphalt shing	JRAL SYSTEMS) Le siding			
SHAPE AND DIMENSIONS OF Rectangular, 16' widt addition to the west	h and 38' depth.	A 7' width by 11'	' depth, 1 story	y frame	
EXTERIOR FEATURES OF NO A modern, broken pedi		ance door			
I hodelii) blokeli pedi	medic over the entr	ance door.			
INTERIOR FEATURES OF NOT				**************************************	
The first floor consists second floor are 2 becapartment with kitcher features of note.	drooms and bath.	In the rear of th	ne first fl∞r i	s an efficiency	
MAJOR ALTERATIONS AND AC For the most part the 77 sq. ft. living room rear.	entire house was	renovated in the	late 1930's wit y sq. ft. addit	th a 1 story tion to the	
PRESENT CONDITION AND US	SE .				
Building vacated on 10	0/2/80 and is in a	state of extreme	e disrepair.		
OTHER INFORMATION AS APP	PROPRIATE				
SOURCES OF INFORMATION (Cultural Resource Surv estate appraisal on 9/	rey for Rt. 130, 91	F, $2/80$, by Histo	ric Śites Resea	rch. Real	